

General Environmental Incident Summary

Incident: 1947 **Date/Time Notice:** 6/18/2013 1300 **DEM Incident No:**

Responsible Party: unknown

Date Incident: 5/16/2013 **Time Incident:** 1110 **Duration:**

County: Williams **Twp:** 155 **Rng:** 103 **Sec:** 17 **Qtr:**

Lat: 48.24140 **Long:** -103.96400 **Method:** Navigation quality GPS

Location Description: N 48.2414
W -103.963983

Submitted By: Scott Stockdill

Affiliation:

Address:

City:

State:

Zip:

Received By:

Contact Person:

unknown

unknown, ND

Distance Nearest Occupied Building: 0.7 Miles

Type of Incident: Unknown Cause

Description of Released Contaminant: Diesel

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Cause of spill unknown

Risk Evaluation:

none

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Spill occurred on gravel road and corresponding ditch.

Action Taken or Planned:

Spill cleaned up with shovels and S200 sprayed on site to aide in biological breakdown of remaining contaminant.

Wastes Disposal Location: unknown

Agencies Involved:

Updates

Date: 5/16/2013

Status: Inspected

Staff: Stockdill, Scott

Updated Volume:

Notes:

N. 48.2414

W -103.963983

Arrived on location at 11:10 AM 5/16/2013.

Diesel spill found while driving along Township road. NDIC supervisor contacted continental who has a drilling rig nearby (Cyclone #25 drilling Stedman 4-24 H1 and 2-24 H2). Continental didn't know how the spill occurred but since they had a cleanup crew nearby they cleaned up the spill using shovels and sprayed S200 on the spill to aid biological breakdown.